

N/A

LMK00304SQX/NOPB

LMK00304SQX/NOPB
 N/A
 IC CLK BUFFER 3:5 3.1GHZ 32WQFN
 RoHS Compliant
 DHL/Fedex/TNT/UPS/EMS



No Picture

□□□ □□□□ □□□□ □□□□. □□□□
 □□□□ □□□□ □□□□.

□□□□ □□□

□ LMK00304SQX/NOPB □□□□ □□□□□□

□□□□ □□□	LMK00304SQX/NOPB
□□□□	N/A
□□□□	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
□□□□□□ □□ □□□ / ROHS □□□	□□□ □□ / RoHS □□□□
□□ □□	
□□□□ - □□□□□	3.15 V ~ 3.45 V
□□□□	Fanout Buffer (Distribution), Multiplexer, Translator
□□□□□ □□□□□ □□□	32-WQFN (5x5)
□□□□□	-
□□□ - □□□□: □□□□	3:5
□□□□	Tape & Reel (TR)
□□□ / □□□	32-WFQFN Exposed Pad
□□□	HCSL, LVCMOS, LVDS, LVPECL
□□□□ □□□ □□□	-40°C ~ 85°C
□□□□□□ □□□	1
□□□□□ □□□□	Surface Mount
□□□□□□ □□□□ □□□ (□□□□□□)	3 (168 Hours)
□□□□□ □□ □□□ / ROHS □□□	Lead free / RoHS Compliant
□□□	CML, HCSL, HSTL, LVDS, LVPECL, SSTL, Crystal
□□□□□ - □□□□	3.1GHz
□□□□ - □□□□-□□□	Yes/Yes
□□□□ □□□□	Clock Fanout Buffer (Distribution), Multiplexer, Translator IC 3:5 3.1GHZ 32-WFQFN Exposed Pad
□□□□□ □□□ □□□	LMK00304

□□□□ □□□□□

LMK00304SQX/NOPB	□ LMK00304SQX/NOPB □□□□	LMK00304SQX/NOPB □□□□
LMK00304SQX/NOPB □□	LMK00304SQX/NOPB □□□□	LMK00304SQX/NOPB □□□
□ LMK00304SQX/NOPB □□□□ □□□ □□□□	LMK00304SQX/NOPB □□□□ □□□□ □□□□	□ LMK00304SQX/NOPB □□□ □□□□
LMK00304SQX/NOPB □□□□□	LMK00304SQX/NOPB □ □□□	LMK00304SQX/NOPB □ □□□
LMK00304SQX/NOPB	□□□□	□ □□□□

□□□□ □□□□

<p>LMK00306SQ/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:7 3.1GHZ 36WQFN □□□□ □□□□ □□: 15141 pcs</p> <p>RFQ</p>	<p>LMK00301SQ/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:10 3.1GHZ 48WQFN □□□□ □□□□ □□: 16276 pcs</p> <p>RFQ</p>
<p>LMK00306SQE/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:7 3.1GHZ 36WQFN □□□□ □□□□ □□: 15164 pcs</p> <p>RFQ</p>	<p>LMK00308SQ/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:9 3.1GHZ 40WQFN □□□□ □□□□ □□: 16225 pcs</p> <p>RFQ</p>
<p>LMK00308EVM/NOPB □□□□□: N/A □□□□□: BOARD EVAL FOR LMK00308 □□□□ □□□□ □□: 337 pcs</p> <p>RFQ</p>	<p>LMK00304SQ/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:5 3.1GHZ 32WQFN □□□□ □□□□ □□: 24218 pcs</p> <p>RFQ</p>
<p>LMK00304SQE/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:5 3.1GHZ 32WQFN □□□□ □□□□ □□: 16840 pcs</p> <p>RFQ</p>	<p>LMK00306EVM/NOPB □□□□□: N/A □□□□□: BOARD EVAL FOR LMK00306 □□□□ □□□□ □□: 409 pcs</p> <p>RFQ</p>
<p>LMK00301SQX/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:10 3.1GHZ 48WQFN □□□□ □□□□ □□: 17670 pcs</p> <p>RFQ</p>	<p>LMK00304EVM/NOPB □□□□□: N/A □□□□□: BOARD EVAL FOR LMK00304 □□□□ □□□□ □□: 425 pcs</p> <p>RFQ</p>
<p>LMK00301SQE/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:10 3.1GHZ 48WQFN □□□□ □□□□ □□: 10236 pcs</p> <p>RFQ</p>	<p>LMK00306SQX/NOPB □□□□□: N/A □□□□□: IC CLK BUFFER 3:7 3.1GHZ 36WQFN □□□□ □□□□ □□: 19578 pcs</p> <p>RFQ</p>